

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2017

Submitted Date:

08/01/2017

Document Number:

687400121**FIELD INSPECTION FORM**

Loc ID 320217 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 1252 CAMERON RDCity: SEQUIM State: WA Zip: 98382**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
		dnr_enforcement@state.co.us	
Axelson, John		john.axelson@state.co.us	
CONN, LIONEL	403-870-5141	lconn@live.ca	<a href="#">inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203084	WELL	PR	12/01/2014	OW	001-08491	LAMBERT 2	PR

**General Comment:**[Within 1000' NTO buffer](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No emergency contact info at wellhead signage		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/30/2017
Type	BATTERY		
Comment:	Signage at battery has no emergency contact info.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/30/2017

**Emergency Contact Number:**

Comment: No emergency contact info on any signage

Corrective Action: Install sign to comply with Rule 210.e.

Date: 08/30/2017

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at wellhead, pumping unit frame around prime mover, under separator fire tube, inside separator cabinet, and behind production tank. See photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	08/30/2017
Type	UNUSED EQUIPMENT		
Comment:	Multile joints of 2"x30' tubing around wellhead.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	
Type	WEEDS		
Comment:	Severely overgrown weeds at wellhead, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/10/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Rod iron		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Battery, separator, and meter run are fenced with 4 strand barbed wire and double green gates.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas fired engine		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Conventional		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	Fiberglass open top. Netting has fallen and is ineffective. See Photo.				
Corrective Action:	Install or repair wildlife protection equipment				Date: 08/10/2017

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berm with production tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Tank paint is out of compliance per rule 804				
Corrective Action:	Repair and paint tanks per Rule 804.				Date: 11/01/2017

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Weeds growing on berms. See Photos.				
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.				Date: 08/10/2017

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 203084 Type: WELL API Number: 001-08491 Status: PR Insp. Status: PR**Producing Well**Comment: No production records since 12/2016.Corrective Action: Submit required Form 7(s) to COGCCDate: 08/30/2017**COGCC Comments**

Comment	User	Date
<u>Location is in disrepair and appears to have not been maintained for several months. See attached PDF for details.</u>	kraicha	08/01/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401361997	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213987</a>
687400122	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213981">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213981</a>