

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

689300023**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
418750 \_\_\_\_\_ O'Donnell, Shaun \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10544Name of Operator: HIGHPOINT ENERGY LLCAddress: 361 71ST AVECity: GREELEY State: CO Zip: 80634**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**24 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		bill@blackrockoil.com	
		mnotter@rocheconstructors.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418740	WELL	PR	05/17/2014	OW	123-31988	RBF 15B	TA
418899	WELL	PR	05/22/2014	OW	123-32060	RBF 24-15D	TA
418900	WELL	PR	07/28/2016	OW	123-32061	RBF 14-15D	TA
419447	WELL	PR	05/23/2014	OW	123-32254	RBF 11-22D	TA
419697	WELL	PR	09/08/2016	OW	123-32323	RBF 13-15D	TA
419699	WELL	PR	05/17/2014	OW	123-32324	RBF 23-15D	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tanks have all placards. Water tank is not labeled		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/01/2017
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
Date:	

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Storage of tubing in unworkmanlike fasion. See attached photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	11/01/2017
Type	WEEDS		
Comment:	Uncontrolled weeds on perimeter of location and inside of tank berm. See attached photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/11/2017
Type	STORAGE OF SUPL		
Comment:	Wellhead production piping is being stored on pallets next to wellheads		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:	2 anchors found on west edge of location. Are not marked adequately. See attached photos		

Corrective Action:	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.		Date:	09/01/2017
Type: Emission Control Device	# 2			
Comment:	Volume pot drain on north ECD is plumbed to drain out on ground . See attached photo			
Corrective Action:	Stop draining volume pot onto ground immediately. Remove plumbing extending out of fence		Date:	08/06/2017
Type: Flow Line	# 3			
Comment:	1-1" unused/unmarked riser at south ECD 2-1" unused/unmarked risers at north end of production tanks See attached photos			
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	3-2" marked/unused risers west of meter run			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

### Location Construction

Location ID: 419699 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective  
Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 418740 Type: WELL API Number: 123-31988 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut in for safety prep

Corrective Action:  Date:

**BradenHead**

Comment: Bradenhead plumbed to surface

Corrective Action:  Date:

Facility ID: 418899 Type: WELL API Number: 123-32060 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut in for safety prep

Corrective Action:  Date:

**BradenHead**

Comment: Plumbed to surface

Corrective Action:  Date:

Facility ID: 418900 Type: WELL API Number: 123-32061 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut in for safety prep

Corrective Action:  Date:

**BradenHead**

Comment: Plumbed to surface

Corrective Action:  Date:

Facility ID: 419447 Type: WELL API Number: 123-32254 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut in for safety prep

Corrective Action:  Date:

**BradenHead**

Comment: Plumbed to surface

Corrective Action:  Date:

Facility ID: 419697 Type: WELL API Number: 123-32323 Status: PR Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut in for safety prep

Corrective Action:

Date:

**BradenHead**Comment: Plumbed to surface

Corrective Action:

Date:

Facility ID: 419699 Type: WELL API Number: 123-32324 Status: PR Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Shut in for safety prep

Corrective Action:

Date:

**BradenHead**Comment: Plumbed to surface

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401361916	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213893</a>
689300024	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213862</a>