

# Inspection Photos

8/7/2017

Operator: DIVERSIFIED OPERATING  
CORPORATION - 24461

Location ID: 305414

Inspection Doc. Number: 675103796  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 305414



**Photo 1:** Photo taken from the southwest end of the location. Photo shows fence gate in disrepair. Advise maintenance.



**Photo 2:** Photo taken from the south end of the location, facing east. Photo shows areas of the location that remain unvegetated with little desirable perennial growth evident. These areas will require additional reclamation work.



**Photo 3:** Photo taken from one of the large bare areas on the south end of the location. Photo shows large areas remain unvegetated with no sign of desirable perennial vegetative germination or growth and establishment.



Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 305414



**Photo 4:** Photo taken from the location, facing east. Photo shows straw wattles on the location that remain in disrepair. Inspection doc. #682501867 required wattles to either be maintained or removed as wattles are considered debris in its current condition. Wattles have not been maintained or removed.



**Photo 5:** Photo taken from the location, facing east. Photo shows straw wattles on the location that remain in disrepair. Inspection doc. #682501867 required wattles to either be maintained or removed as wattles are considered debris in its current condition. Wattles have not been maintained or removed.



**Photo 6:** Photo taken from the southeast end of the location, facing west. Photo shows areas of the location that remain unvegetated with little desirable perennial growth evident. These areas will require additional reclamation work.



Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 305414



**Photo 7:** Photo taken from access road, east of the location. Inspection doc. #682501867 required operator to removed cattle guard. Photo shows cattle guard that has not been removed.



**Photo 8:** Photo taken from access road, east of the location. Inspection doc. #682501867 required operator to removed cattle guard. Photo shows cattle guard that has not been removed. Note label on cattle guard says "Noble Energy Inc.".