

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2017

Submitted Date:

08/08/2017

Document Number:

666803456**FIELD INSPECTION FORM**

Loc ID 334893 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Contact, General		cogcc.inspections@encana.com	
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262978	WELL	PR	10/31/2002	GW	045-08087	HMU 10-7 (F10W)	PR
262979	WELL	PR	11/12/2002	GW	045-08088	HMU 10-12(F10W)	PR
262980	WELL	PR	02/01/2008	GW	045-08089	HMU 10-6 (F10W)	PR
262981	WELL	PR	06/16/2005	GW	045-08090	HMU 10-7 (F10)	PR
262982	WELL	PR	05/10/2009	GW	045-08091	HMU 10-11 (F10W)	PR

General Comment:Shared facilities with location ID 334952

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	NTO, Comply with Rule 603.f . see photos		
Corrective Action:	24 hrs to lock out tag out. 30 days to remove riser		Date: 09/07/2017
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST		39.462578,-107.763236
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	262978	Type:	WELL	API Number:	045-08087	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	262979	Type:	WELL	API Number:	045-08088	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	262980	Type:	WELL	API Number:	045-08089	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	262981	Type:	WELL	API Number:	045-08090	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	262982	Type:	WELL	API Number:	045-08091	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
Rip Rap	Pass					
Seeding	Pass					
Sediment Traps	Pass					
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: [Sediment leaving location,](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 09/07/2017

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803457	NT0 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220380
666803458	NT0 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220381
666803459	NT0 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220382
666803460	Storm 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220383
666803461	storm 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220384