

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2017

Submitted Date:

08/08/2017

Document Number:

666803470**FIELD INSPECTION FORM**

Loc ID 334940 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------------------|
| Leonard, Mike | | mike.leonard@state.co.us | |
| Contact, General | | cogcc.inspections@encana.com | |
| Kellerby, Shaun | | Shaun.Kellerby@state.co.us | NW Field Supervisor |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 267970 | WELL | PR | 02/19/2004 | GW | 045-09226 | HMU 3-15A (I3) | PR |
| 267974 | WELL | PR | 02/19/2004 | GW | 045-09229 | HMU 3-16 (I3) | PR |
| 267982 | WELL | PR | 02/19/2004 | GW | 045-09236 | HMU 3-10 (I3) | PR |
| 268005 | WELL | PR | 02/19/2004 | GW | 045-09238 | HMU 3-15 (I3) | PR |
| 268006 | WELL | PR | 02/19/2004 | GW | 045-09239 | HMU 3-14A (3) | PR |

General Comment:Shared tank battery with location ID 334911

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

| | | | |
|---------------------------------|---|-------|------------------|
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # | | |
| Comment: | NTO, Comply with Rule 603.f . see photos | | |
| Corrective Action: | 24 hrs to lock out tag out. 30 days to remove riser | | Date: 09/07/2017 |
| Type: Vertical Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 2 | 400 BBLS | STEEL AST | | 39.473159,-107.755940 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

Inspector Name: Murray, Richard

| | | | | | |
|--------------------|----------|------------------|-----------------|----------|-----------------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 3 | 500 BBLs | STEEL AST | | 39.473319,-107.755871 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Insufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 267970 | Type: | WELL | API Number: | 045-09226 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 267974 | Type: | WELL | API Number: | 045-09229 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 267982 | Type: | WELL | API Number: | 045-09236 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 268005 | Type: | WELL | API Number: | 045-09238 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 268006 | Type: | WELL | API Number: | 045-09239 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |

| Environmental | |
|------------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): YES | |
| Comment: | |
| Pilot: ON | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Sediment Traps | Pass | | | | | |
| Gravel | Pass | | | | | |
| Berms | Pass | | | | | |
| | | Gravel | Pass | | | |
| | | Culverts | Pass | | | |
| | | Ditches | Pass | | | |
| Ditches | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 666803471 | NT0 1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220613 |
| 666803472 | NT0 3 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220614 |
| 666803473 | NT0 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220615 |