

Location

Lease Road:			
Type	Access		
comment:	Forest service road		
Corrective Action	L		Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Observed abandoned flowline/pipeline risers		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Observed abandoned flowline/pipeline risers Abandoned flowline riser and meter house on NW corner of location (39.120311,-107.484586). See attached photo.		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

COGCC Comments

Comment	User	Date
Joint inspection with COGCC supervisor Steve Labowskie.	browninc	08/02/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401363765	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4215302
680401724	7/26/2017 inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4215298