

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:
	Type	Main	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No	
Comment:	<input type="text"/>
<input type="checkbox"/> Multiple Spills and Releases?	

Fencing/:			
	Type	WELLHEAD	
	Comment:	Panel fence	
	Corrective Action:		Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Unused pump jack on N side of location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: <u>11/02/2017</u>
Type: Flow Line	# 1		
Comment:	Unused 1" flowline riser at wellhead. See photo.		
Corrective Action:			Date:

Venting:			
	Yes/No	NO	
	Comment:		
	Corrective Action:		Date:

Flaring:			
Type			

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283607 Type: WELL API Number: 051-06070 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Ditches	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Joint inspection with COGCC supervisor Steve Labowskie.	browninc	08/02/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401363768	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4215305
680401726	7/26/2017 inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4215300