

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2017

Submitted Date:

08/02/2017

Document Number:

687400129**FIELD INSPECTION FORM**

Loc ID 320129 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 1252 CAMERON RDCity: SEQUIM State: WA Zip: 98382**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
CONN, LIONEL	403-870-5141	lconn@live.ca	<a href="#">inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202757	WELL	PR	07/31/2008	OW	001-08162	CROFF 12-5	PR

**General Comment:**[Within 1000' NTO buffer](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signage missing emergency contact info. See photos.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/31/2017

Emergency Contact Number:			
Comment:	Signage has no emergency contact info		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 08/31/2017

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around wellhead, see photo.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date:

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 202757 Type: WELL API Number: 001-08162 Status: PR Insp. Status: PR**Producing Well**Comment: [Production not reported since 1/2016.](#)Corrective Action: [Submit required Form 7\(s\) to COGCC](#)Date: 08/31/2017**COGCC Comments**

Comment	User	Date
<a href="#">Well commingles with Brink S2 (001-09363), LenartS1 (001-09362), Elms 12-4 (001-08153) and Reinholt 12-6 (001-08163). All surface equipment and related corrective actions as well as unidentified risers at battery will be called out on the Reinholt 12-6 inspection form, DOC#687400118.</a>	kraicha	08/02/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401363009	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214809">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214809</a>
687400130	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214804">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214804</a>