

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/03/2017

Submitted Date:

08/09/2017

Document Number:

674901876**FIELD INSPECTION FORM**
 Loc ID 325326 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	SW Insp Reports
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115505	PIT				-	SPRING HOLLOW MAC 1	EI
214567	WELL	PR	03/01/2011	OW	067-06170	SPRING HOLLOW MAC 1	EI

General Comment:

On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Spring Hollow Mac #1. For the most recent field inspection report for this facility, please refer to document #667100134.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near well head.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	400 bbl. AST does not have a label or placard.			
Corrective Action:	Install sign to comply with Rule 210.d.		Date:	10/09/2017
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Well head is stained and wet.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d		Date:	09/11/2017
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil beneath both load out valves on ASTs at tank battery.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date:	09/11/2017
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained soil around well head.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date:	09/11/2017
In Containment: No				
Comment:				
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Guard fencing.			
Corrective Action:			Date:	
Equipment:				corrective date
Type: Pump Jack	# 1			
Comment:	Electric motor.			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		37.127720,-108.089897
Comment: Reportedly, tank is periodically used to isolate well from tank battery. Currently not connected to well.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: No secondary containment present.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.4.				Date: <u>09/11/2017</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		37.128226,-108.092053
Comment: Tank battery services Spring Hollow Mac #1, #2, and #3 wells.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	115505	Type:	PIT	API Number:	-	Status:		Insp. Status:	EI
Facility ID:	214567	Type:	WELL	API Number:	067-06170	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 115505 Lat: 37.127617 Long: -108.089975

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Document #705194 dated 10/31/89 indicates that no pits were present at the time of the lease inspection.

Corrective Action

Date: g**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Spring Hollow Mac #1. For the most recent field inspection report for this facility, please refer to document #667100134. A 400 bbl. AST on location that is reportedly periodically used to isolate the well from the tank battery, does not have labels, placards, or secondary containment. No indication of pit #115505 exists on location. Document #705194 indicates that no pit was present during that 10/31/89 lease inspection. No pits were visible while reviewing historical aerial imagery. The well head is wet and stained soil is present nearby.	hughesj	08/09/2017

Attached Documents

You can go to COGCC Images ([https://cogcc.state.co.us/weblink/](https://cogcc.state.co.us/webblink/)) and search by document number:

Document Num	Description	URL
674901877	Well head is wet and surrounded by stained soil.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222232
674901879	Spring Hollow Mac #1 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222233
674901880	Tank battery with impacted material beneath valves.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222234