



photo 1: Facing south toward the former tank battery site. It appears the pipeline infrastructure is midstream gathering.



photo 2: Facing toward the south side of the former tank battery site. The tanks remain and there is undesirable vegetation growth throughout the site.



photo 3: South side of the former tank battery site. There is a cattle guard, soil pile, and tanks that remain.



photo 4: There is List B noxious weeds (Musk thistle) throughout the tank battery site which are beginning to disperse seed.



photo 5: Facing west toward the cultivated field where the site is located.



photo 6: The electric utilities remain at the location and the location has not been reclaimed per rule 1004.