

Inspection Photos  
Location Name: Bingman 1-14  
API: 05-081-06954



**Photo 1. Location overview taken at entrance facing west.**



**Photo 2. Unconsolidated berm with plastic liner pieces mixed in. Weeds in berm.**

Inspection Photos  
Location Name: Bingman 1-14  
API: 05-081-06954



Photo 3. 2 – 2” steel risers at 40.38894, -108.13606.  
Weeds.



Photo 4. 1 – 2” steel riser in tank berm. Weeds.

Inspection Photos  
Location Name: Bingman 1-14  
API: 05-081-06954



**Photo 5. Former land farm area with apparent recent work.**



**Photo 6. View of pit taken at 40.38910, -108.13656 facing northwest.**