

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2017

Submitted Date:

08/10/2017

Document Number:

689800094

**FIELD INSPECTION FORM**

Loc ID 313094 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10428  
Name of Operator: DIVERSIFIED ENERGY LLC  
Address: 19501 E MAIN STREET #200  
City: PARKER State: CO Zip: 80138

**Findings:**

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Haack, Jason	303-995-0826	jhaack@oagproduction.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223587	WELL	PR	11/01/2014	OW	081-06954	BINGMAN 1-14	SI

**General Comment:**

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road appears to have been graded recently. Plastic liner pieces were observed on entire roadway from gate to location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	303-995-0826		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Type	TRASH		
Comment:	Plastic liner pieces in tank berm and around location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Flow Line	#		
Comment:	2 - 2" steel risers observed at 40.38894, -108.13606 and 1 - 2" steel riser observed in tank berm not locked out tagged out.		
Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."		Date: 08/21/2017
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		40.389110,-108.136050
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate
Comment:	Berm is not consolidated. Plastic liner pieces incorporated into loose soil.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Comply with Rule 603.f .			Date: 08/21/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient		Inadequate	
Comment:	Berm is not consolidated. Plastic liner pieces incorporated into loose soil.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Comply with Rule 603.f .			Date:	08/21/2017

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 223587 Type: WELL API Number: 081-06954 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326. Well has been shut-in since September 2015. MIT will be needed this September 2017.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed.  
No apparent soil migration; erosion or soil movement.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID: <u>285519</u>	Lat: <u>40.389080</u>	Long: <u>-108.136300</u>
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: c

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	285519	200092804	

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">The land farm area mentioned in previous inspections appears to have recently been removed. Please follow environmental Corrective Actions found in inspection report document number 677900246 in addition to the ones found in this report.</span>	waldrone	08/10/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689800129	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222875">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222875</a>