



**Photo 1: View of the project area from the northeastern corner facing center.**



**Photo 2: View of the eastern portion of the project area from the northeastern corner of the well pad facing southward. This slope is not stabilized and is eroding.**



**Photo 3: View of the northern portion of the project area from the northeastern corner of the well pad facing westward.**



**Photo 4: View of erosional channel in the northern portion of the project area, approximately 2 feet wide and 8 to 12 inches deep, facing upstream onto the well pad.**



**Photo 5: View of erosional channel shown in Photo 4 facing downstream in the northern portion of the project area.**



**Photo 6: View of the southern portion of the project area from the eastern edge facing southwestward. Rilling is occurring on the cut-slope.**