

Inspection Photos  
Location Name: Wolf Mountain 15-2-7-87  
API: 05-107-06222



**Photo 1. Overview of location taken at entrance facing north.**



**Photo 2. Fresh gravel with staining visible underneath. Lube oil stored without containment on left side of pump jack.**

Inspection Photos  
Location Name: Wolf Mountain 15-2-7-87  
API: 05-107-06222



**Photo 3. Close-up of ongoing leak and staining at wellhead.**



**Photo 4. 2" steel riser not in use. Stained soil covered by fresh gravel.**