

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2017

Submitted Date:

08/10/2017

Document Number:

673715950**FIELD INSPECTION FORM**
 Loc ID 442484 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	<a href="#">Production</a>
Strickler, Robert		Robert.D.Strickler@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	<a href="#">Regulatory Supervisor</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442485	WELL	DG	05/09/2017	LO	005-07242	Montezuma 4-64 18-13 4H	WO

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	2 open tops for first flowback, 2 produced water tanks and 2 crude oil tanks, signs in process		
Corrective Action:		Date:	
Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

### Location Construction

Location ID: 442485 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** Flow back will have combustor for tank vents and salable gas will go to sales line. Sound walls are on the north and east sides of location. Production tanks (4-400 BBLs) at tank battery are being installed on location at time of inspection-not currently in operation.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 442485 Type: WELL API Number: 005-07242 Status: DG Insp. Status: WO**BradenHead**

Comment: no gauge on Bradenhead at time on inspection (well is SI). Operator on location said that it would be connected during flowback.

Corrective Action:

Date:

**Completion**Operation: FlowbackDate Flowback: 08/10/2017Contractor: Select

Comment: Water from Pur Cycle. On 8/7/2017 operator was waiting on combustor parts prior to start up. Flowback scheduled to start 8/10/2017.

Corrective Action:

Date: