

Inspection Photos
Location FARM RANCH EXP 2
API:05-001-07672



TANK BATTERY SIGN



LOAD LINE VALVE NO CAP ON VALVE and stained soil