

- Annala Federal A 1 05-067-07741



Photo 1: Wellhead sign.

- Annala Federal A 1 05-067-07741



Photo 2: Mulch piles on SE corner.

- Annala Federal A 1 05-067-07741



Photo 3: Right side view of weeds and grass in produced water tank base area.

- Annala Federal A 1 05-067-07741



Photo 4: Left side view of weeds and grass in produced water tank base area.

- Annala Federal A 1 05-067-07741



Photo 5: Failed waddle, erosion channel, and dumped wood.

- Annala Federal A 1 05-067-07741



Photo 6: Erosion channel and additional wood on W perimeter.

- Annala Federal A 1 05-067-07741



Photo 7: Wood debris.

- Annala Federal A 1 05-067-07741



Photo 8: Erosion channel and additional cut wood dumped on location.

- Annala Federal A 1 05-067-07741



Photo 9: Full waddle and erosion channel.

- Annala Federal A 1 05-067-07741



Photo 10: Dumped wood and debris in drainage on N perimeter.

- Annala Federal A 1 05-067-07741



Photo 11: Impacted soil at wellhead.

- Annala Federal A 1 05-067-07741



Photo 12: Canada Thistle on location.

- Annala Federal A 1 05-067-07741



Photo 13: Muffler and connections at pump jack motor.

- Annala Federal A 1 05-067-07741



Photo 14: Flex pipe connection to in-line muffler.

- Annala Federal A 1 05-067-07741



Photo 15: Flex pipe connection at back of in-line muffler.

- Annala Federal A 1 05-067-07741



Photo 16: Flex pipe fed under sound wall.

- Annala Federal A 1 05-067-07741



Photo 17: Photo of pump jack with sound walls taken from SE corner of location.

- Annala Federal A 1 05-067-07741



Photo 18: Sound meter set up just out from SE corner of location.