

Location

| | | | |
|--------------------|---------------------------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | | | |
|----------------------|--------------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease by water tank | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metla sign by water tank | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------------|------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | VGS in fiberglass shed | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | | | |
|-------------------------|----------------------------------|----------|----------------|---------|-----------------------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.856740,-102.167240 |
| Comment: | Fiberglass water tank 50% buried | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition:

| | |
|--------------------------|--|
| Other (Content) | |
| Other (Capacity) 210bbbs | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 277070 Type: WELL API Number: 125-09198 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central meter run for \(Cranmer 1-27, 4-27, 31-27, 33-27, Heath 42-27, 43-27, Renzelman 41-27\) 1500' W @ Cranmer 1-27](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: [Access has erosion through creek and needs maintenance](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401366159 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217667 |