

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2017

Submitted Date:

07/27/2017

Document Number:

681902243**FIELD INSPECTION FORM**

Loc ID 434526 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434733	WELL	XX	07/30/2015	LO	123-38301	Pratt 4C-29H-P168	XX

**General Comment:**

**Inspected Facilities**

Facility ID: 434733 Type: WELL API Number: 123-38301 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: Ensign 153 Pusher/Rig Manager: John Holand  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: Waste Connections

**Comment:** Drilling surface casing. Derrick screened for fugitive light mitigation. Sound mitigation in place. Chemicals properly stored. Vehicle tracking pads in use. BOPs tested. No conditions observed that exceed COGCC rules.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401365578	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217185</a>
681902244	Rig	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217180</a>