

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/03/2017

Submitted Date:

08/11/2017

Document Number:

674901890**FIELD INSPECTION FORM**
 Loc ID 325164 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	918-749-8828	lcallahan3@swbell.net	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	SW Insp Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214178	WELL	SI	02/01/2017	OW	067-05498	LONG & SCHLUTER 1	EI

General Comment:

On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Long and Schluter #1. For the most recent field inspection report of this facility, please refer to document #685301167.

Location					
<u>Lease Road:</u>					
Type	Access				
comment:					
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
<u>Signs/Marker:</u>					
Type	WELLHEAD				
Comment:	Free standing sign next to pump jack.				
Corrective Action:					Date:
Type	BATTERY				
Comment:	Free standing sign located near AST.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
<u>Good Housekeeping:</u>					
Type					
Comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
<u>Spills:</u>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<u>Fencing/:</u>					
Type	PUMP JACK				
Comment:	Guard fencing on pump jack.				
Corrective Action:					Date:
<u>Equipment:</u>					
					corrective date
Type: Pump Jack	# 1				
Comment:	Electric motor.				
Corrective Action:					Date:
<u>Tanks and Berms:</u>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.124992,-108.089949
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214178	Type:	WELL	API Number:	067-05498	Status:	SI	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Long and Schluter #1. For the most recent field inspection report of this facility, please refer to document #685301167. A Professional Well Services work over rig and crew were on location during this inspection. Glenn Stevens, Williford Resources LLC representative, was also on site during this inspection. In addition to the work over rig, ancillary equipment included a skid mounted mud pit and three skid mounted compressors.	hughesj	08/11/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901891	L and S #1 location photo with workover rig.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224588
674901892	L and S #1 pump jack and well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224589
674901893	L and S #1 300 bbl. AST.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224590