

Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Wellhead sign looking west



Wellhead looking west

Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Wellhead looking east



Battery looking north

Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Tank battery looking north



Actively growing weeds west side of separator



Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



East side of separator looking north. Actively growing weeds



Southeast edge of location looking west. Actively growing weeds

Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Location washing out northeast of tank battery (1/2 spots)



Location washing out northeast of tank battery (2/2 spots)



Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Lease road washing out headed northeast before curve



Lease road looking south before curve. Standing water actively draining through lease road to the east



Inspection Photos
Location Name: Raisley 21-34
API: 05-123-16741



Battery entrance looking south. Lease road washing out, carrying sediment off.



Lease road looking south before curve