



photo 1: Facing west along the former access road. The field has recently been plowed.



photo 2: The well site has not been plowed and properly decompacted.



photo 3: There is wood boards and various debris that remains.



photo 4: Facing back east at the well site.