

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2017

Submitted Date:

08/11/2017

Document Number:

689300048

**FIELD INSPECTION FORM**

Loc ID 322590 Inspector Name: O'Donnell, Shaun On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Precup, Jim		james.precup@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243902	WELL	PR	06/28/1985	GW	123-11694	DOS RIOS 1-33	SI

**General Comment:**

*(This area is intentionally left blank for general comments.)*

Location			
<b>Lease Road:</b>			
	Type	Access	
	comment:	Actively growing weeds going to wellhead from entrance. Needs to be controlled. See attached photos	
	Corrective ActionL	See corrective action under Housekeeping.	Date:
	Type	Main	
	comment:	Adequate	
	Corrective ActionL		Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Adequate	
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:	Adequate	
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:	Adequate	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	Adequate	
	Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
	Type	WEEDS	
	Comment:	Actively growing weeds around the perimeter of location. Actively growing weeds around the perimeter of the wellhead and lease road northeast of entrance to wellhead. Needs to be controlled. See attached photos.	
	Corrective Action:	Comply with Rule 603.f .	Date: <u>08/21/2017</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
	Type	WELLHEAD	
	Comment:	Steel pipe	
	Corrective Action:		Date:
	Type	TANK BATTERY	

Comment:	Steel wire		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Steel wire		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with crude tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.352830,-104.779140
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 243902 Type: WELL API Number: 123-11694 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is configured to produce. Not producing at the time of inspection. Showing recorded production as of May 2017

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300049	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224712">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224712</a>