

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 1: Produced water tank has capacity and contents

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 2: Decals from prior operator have been obscured

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 3: Battery sign is for current operator

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 4: Sign at produced water vault is for current operator

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison




Photo 5: Wellhead sign is for current operator

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 6: Stained soil at drain has been removed or remediated

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo from prior inspection for comparison



Photo 7: Stained soil at exhaust

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo 8: Stained soil in engine house