

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2017

Submitted Date:

08/14/2017

Document Number:

674901898

FIELD INSPECTION FORM

Loc ID 325074 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 14 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213931	WELL	PA	11/11/2011	GW	067-05202	SOUTHERN UTE 32-8 1-1	EI
257024	WELL	PR	11/07/2013	GW	067-08293	SOUTHERN UTE 32-8; 1-7	EI
451653	SPILL OR RELEASE	AC	08/08/2017		-	SPILL/RELEASE POINT	EI

General Comment:

On August 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute 32-8 #1-7. For the most recent field inspection report for this facility, please refer to document #685301776. Spill/release point ID #451653 has been created in the COGIS database for a release discovered on 8/4/17.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator. Old sign remains on site.		
Corrective Action:			Date:
Type	OTHER		
Comment:	PA marker for 067-05202.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water	Flow Line		
Comment:	Spill ID #451653.		
Corrective Action:	Submit supplemental spill report per Rule 906.b.		Date: 08/14/2017

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Orange safety fencing around perimeter of excavation.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Stock panel fencing and guard fencing.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Steel pipe barricade around PA marker for 067-05202.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 213931 Type: WELL API Number: 067-05202 Status: PA Insp. Status: EI

Facility ID: 257024 Type: WELL API Number: 067-08293 Status: PR Insp. Status: EI

Facility ID: 451653 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Refer to spill/release point ID #451653 for more information regarding this release.

Corrective Action: Submit supplemental spill report per Rule 906.b.

Date: 08/14/2017

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: [Erosion along eastern edge of pad.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 09/14/2017

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On August 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute 32-8 #1-7. For the most recent field inspection report for this facility, please refer to document #685301776. Spill/release point ID #451653 has been created in the COGIS database for a release discovered on 8/4/17. Construction crews were on site fabricating a new section of flow line. A trench has been opened up from the separator to the well head where the release occurred.</p>	hughesj	08/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901899	Erosion along eastern edge of pad.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225733
674901900	Erosion on eastern edge of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225734
674901901	Excavated area where release occurred.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225735
674901902	Welders fabricating new flow line.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225736
674901903	Excavated area near separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225737