

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2017

Submitted Date:

08/14/2017

Document Number:

678300865

FIELD INSPECTION FORM

Loc ID 317711 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|-------------------------------|------------------------------|
| Schneider, Paul | 303-868-6665 | Paul.Schneider@anadarko.com | Sr. Staff EHS Representative |
| | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|------------------------------|-------------|
| 451666 | TANK BATTERY | AC | 03/19/2014 | | - | 1415 Corp Gas Unit 1 battery | EI |

General Comment:

well at same locationn 1415 Corp Gas Unit 1 (123-07622) was plugged and abandoned in 2014. tank battery has been removed. COGCC inspection records indicate battery had a partly buried produced water tank (fiberglass and 75bbl size).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|-----------|----------------|---------|------------------|
| PRODUCED WATER | 0 | <100 BBLS | PBV FIBERGLASS | | , |
| Comment: | reported in Inspection 60000950 performed on 03/19/2014 and is not now present as shown in attached photo. No record of form 27 submittal to document removal of PW PBV as required by rule 905.b. ...buried or partially buried produced water vessels, and emergency pits shall be closed in accordance with an approved Site Investigation and Remediation Workplan, Form 27. | | | | |
| Corrective Action: | Submit documentation to support closure by form 27. | | | | Date: 09/14/2017 |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
| | | | | |
| Comment: | <input type="text"/> | | | |
| Corrective Action: | <input type="text"/> | | | Date: <input type="text"/> |

Venting:

| | | |
|--------------------|----------------------|----------------------------|
| Yes/No | <input type="text"/> | <input type="text"/> |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Flaring:

| | |
|--------------------|----------------------------|
| Type | <input type="text"/> |
| Comment: | <input type="text"/> |
| Corrective Action: | Date: <input type="text"/> |

Inspected FacilitiesFacility ID: 451666 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 678300866 | location photo 9Aug2017 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226010 |