

**Inspection Photos**  
**Location Name: Mustang Resources LLC**  
**API05-045-06557**



**Entrance looking south towards residence**



**Entrance looking northeast towards location**



**Inspection Photos**  
**Location Name: Mustang Resources LLC**  
**API05-045-06557**



**Distance from tank relief valve**



**Small tank with no labels or placards noted in previous inspection as Corrective actions needed**



**Inspection Photos**  
**Location Name: Mustang Resources LLC**  
**API05-045-06557**



**Wellhead looking back to entrance**

