

**Inspection Photos**  
**Location Name: Dolan Ranches #13-27**  
**API: 05-123-07364**



**Photo from prior inspection for comparison**



**Photo 1: Weeds around wellhead and engine. Cannot determine soil status around wellhead.**

**Inspection Photos**  
**Location Name: Dolan Ranches #13-27**  
**API: 05-123-07364**



**Photo from prior inspection for comparison**



**Photo 2: Pit liner sagging**

**Inspection Photos**  
**Location Name: Dolan Ranches #13-27**  
**API: 05-123-07364**



**Photo from prior inspection for comparison**



**Photo 3: Pit liner sagging**

**Inspection Photos**  
**Location Name: Dolan Ranches #13-27**  
**API: 05-123-07364**



**Photo from prior inspection for comparison**



**Photo 4: Prior operator signage removed**

Inspection Photos  
Location Name: Dolan Ranches #13-27  
API: 05-123-07364



Photo from prior inspection for comparison



Photo 5: Tanks have placarding, contents, capacities. Operator signage and emergency number at battery. Weeds in berms

**Inspection Photos**  
**Location Name: Dolan Ranches #13-27**  
**API: 05-123-07364**



**Photo 6: Stained soil at engine exhaust**