

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 2. 2 -2" steel risers and 1 – 1" steel riser.



Photo 3. 2 – 1" steel risers and 1 – 2" steel riser.

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 4. Tank with no label and no berm. Container with no secondary containment next to tank.



Photo 5. Example of erosion occurring on west side of location.