



photo 1: A section of the pipe riser has been removed since the previous inspection. The remaining riser has been painted fluorescent. Lat/Long:39.98959,-104.54693



photo 2: Facing west toward the area of the well site. A crop has not been planted this season.