

Interim Reclamation and Stormwater Inspection

August 15, 2017

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 418125

Weld County, CO

NWSE Section 3 T11N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LAZY D ZN #03-09
Location ID: 418125



Photo 1. Photo taken from the entrance of location, facing East. Interim reclamation activities have been performed and are in process. Appears erosion controls have been installed to stabilize the seeded soil. Did not observe any germination throughout the interim area.



Photo 2. Photo taken from the entrance of location, facing Southeast. Interim reclamation activities have been performed and are in process. Appears erosion controls have been installed to stabilize the seeded soil. Did not observe any germination throughout the interim area.

Inspection Photos
Location Name: LAZY D ZN #03-09
Location ID: 418125



Photo 3. Photo taken from the entrance of location, facing South. Interim reclamation activities have been performed and are in process. Appears erosion controls have been installed to stabilize the seeded soil. Did not observe any germination throughout the interim area.



Photo 4. Photo taken from the entrance of location, facing Southwest. Interim reclamation activities have been performed and are in process. Appears erosion controls have been installed to stabilize the seeded soil. Did not observe any germination throughout the interim area.

Inspection Photos
Location Name: LAZY D ZN #03-09
Location ID: 418125



Photo 5. Photo taken from the western interim area, facing West. Appears erosion controls have been installed to stabilize the seeded soil. Did not observe any germination throughout the interim area.



Photo 6. Close-up photo taken documenting that no germination was observed.