



**photo 1:** Facing southwest toward the former tank battery site. The tank has been removed since the previous inspection.



**photo 2:** Facing southwest toward the former well site.



**photo 3:** This pipe riser still remains at the location Lat/Long:39.90421,-10454758.



**photo 4:** The fence and some of the equipment appears to have been removed.



**photo 5:** It appears that the noxious weed control was performed however there is some weeds that are re-sprouting.



**photo 6:** Northwest side of the location facing southeast. There is a metal sticking out of the ground that needs to be removed.