

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2017

Submitted Date:

08/15/2017

Document Number:

666803497**FIELD INSPECTION FORM**
 Loc ID 335055 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Leonard, Mike		mike.leonard@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268723	WELL	PR	03/01/2017	GW	045-09287	CSF 22C-07-07-91	PR
279971	WELL	PR	03/01/2017	GW	045-11120	CSF 11B-07-07-91	PR
279974	WELL	PR	03/01/2017	GW	045-11122	CSF 21B-07-07-91	PR
283836	WELL	PR	04/01/2017	GW	045-11983	CSF 31B-07-07-91	PR
283837	WELL	PR	04/01/2017	GW	045-11984	CSF 32B-07-07-91	PR
298151	WELL	PR	04/01/2017	GW	045-17084	CSF 21C-07-07-91	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser

Corrective Action: Comply with Rule 603.f .

Date:

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator # 5

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 5

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.462836,-107.519636

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
		Culverts	Pass			
		Ditches	Pass			
Berms	Pass					
Gravel	Pass					
Seeding	In Process					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803498	URSA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4228118