

# Inspection Photos

8/14/2017

Operator: SMITH OIL PROPERTIES INC - 79905

API: 123-08177

Inspection Doc. Number: 675103860

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: SMITH OIL PROPERTIES INC - 79905  
Location ID: 123-08177



08.14.2017 08.43

**Photo 1:** Photo taken from the east end of the battery facility. Photo of one of the two signs for an active well this battery serves.



08.14.2017 08.43

**Photo 2:** Photo taken from the east end of the battery facility. Photo shows the second sign for an active well this battery serves


## Inspection Photos

Operator: SMITH OIL PROPERTIES INC - 79905

Location ID: 123-08177



**Photo 3:** Photo taken from the central area of the battery facility, facing north. Photo shows risers at the battery. Inspection doc. #682502037 required operator to comply with reclamation requirements and the 2017 Flowline NTO to remove the risers. Operator appears to have only sprayed "In Use" on five (5) of the seven (7) risers visible (risers labeled 1-5). Risers labeled "In Use" will require pressure testing.



**Photo 4:** Photo taken from the central area of the battery facility, facing north. Photo shows risers at the battery. Inspection doc. #682502037 required operator to comply with reclamation requirements and the 2017 Flowline NTO to remove the risers. Operator appears to have only sprayed "In Use" on five (5) of the seven (7) risers visible (risers labeled 1-5). Risers labeled "In Use" will require pressure testing.



**Photo 5:** Photo taken from the central area of the battery facility. Photo shows risers at the battery. Inspection doc. #682502037 required operator to comply with reclamation requirements and the 2017 Flowline NTO to remove the risers. Riser seen here does not appear to be in use and will need to be removed.



**Photo 6:** Photo taken from the central area of the battery facility. Photo shows risers at the battery. Inspection doc. #682502037 required operator to comply with reclamation requirements and the 2017 Flowline NTO to remove the risers. Riser seen here does not appear to be in proper function condition and needs to be removed.