

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2017

Submitted Date:

08/16/2017

Document Number:

675103860

**FIELD INSPECTION FORM**

Loc ID 318012 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 79905  
Name of Operator: SMITH OIL PROPERTIES INC  
Address: PO BOX 219  
City: BYERS State: CO Zip: 80103

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
		smithoilprop@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240389	WELL	IJ	11/03/1989	ERIW	123-08177	PRESTON (LANYARD WATERFLOOD) 42-18	IJ

**General Comment:**

This is a follow-up inspection to doc. #682502037 in regards to seven (7) pipe risers at the tank battery facility. Inspection Doc. #Inspection Doc. #682502037 was a reclamation and 2017 Flowline NTO inspection associated with the PAd well 123-08175. These risers are now being addressed with this inspection report for tracking purposes regarding UIC, and because the Preston 42-8 is an active IJ well related to the tank battery facility in question.

Tank battery facility associated with the UIC #150166 Lanyard Unit; signs at facility indicate battery also serves the Andrews 23-18 (123-08129). Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume	corrective date
Type: Flow Line	# 5		
Comment:	Inspection Doc. #682502037 required operator to remove seven (7) pipe risers at the tank battery location. Of the seven, operator has sprayed "In Use" on five (5) of the larger risers. See Photos 3 and 4 in the attached photo document. These risers will require pressure testing.		
Corrective Action:	Pressure test the five risers at the battery facility labeled "In Use" and submit the results attached to the Field Inspection Report Resolution (FIRR).		Date: <u>09/16/2017</u>
Type: Flow Line	# 2		
Comment:	Inspection Doc. #682502037 required operator to remove seven (7) pipe risers at the tank battery location. Two risers remain, are not labeled as "in use". The riser seen in photo 5 of the attached photo document does not appear to be in use, and the riser in photo 6 does not appear to be in proper functioning condition. These risers need to be removed. Original CA and CA date remains in place.		
Corrective Action:	Remove risers in accordance to COGCC rules and requirements.		Date: <u>06/30/2017</u>

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240389 Type: WELL API Number: 123-08177 Status: IJ Insp. Status: IJ

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103861	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4228361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4228361</a>