



photo 1: Facing northeast toward the location. The location has been built and has not been reclaimed.



photo 2: Facing northwest along the topsoil pile at the west side of the location. There are weed issues and signs of erosion occurring along the topsoil pile.



photo 3: There is a pit at the east side of the location which has torn liner debris.



photo 4: Facing south at the east side of the location toward the pit.



photo 5: A second pit remains open at the northeast side of the location.



photo 6: Northeast side of the location facing southwest.



photo 7: There is signs of erosion occurring off the northeast side of the location



photo 8: Facing west at the surrounding undisturbed reference area.