

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2017

Submitted Date:

08/10/2017

Document Number:

689800094**FIELD INSPECTION FORM**Loc ID 313094 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10428Name of Operator: DIVERSIFIED ENERGY LLCAddress: 19501 E MAIN STREET #200City: PARKER State: CO Zip: 80138**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Haack, Jason	303-995-0826	jhaack@oagproduction.com	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223587	WELL	PR	11/01/2014	OW	081-06954	BINGMAN 1-14	SI
285519	PIT	AC	07/07/2006		-	BINGMAN 1-14	AC

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road appears to have been graded recently. Plastic liner pieces were observed on entire roadway from gate to location.		
Corrective Action	Comply with Rule 603.f .	Date:	08/21/2017

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-995-0826

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Plastic liner pieces in tank berm and around location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/04/2017
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/04/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	PIT		
Comment:			

Corrective Action:		Date:
Equipment:		corrective date
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Flow Line	#	
Comment: 2 - 2" steel risers observed at 40.38894, -108.13606 and 1 - 2" steel riser observed in tank berm not locked out tagged out.		
Corrective Action: "Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."		Date: 08/21/2017
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		40.389110,-108.136050
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate
Comment: Berm is not consolidated. Plastic liner pieces incorporated into loose soil.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Comply with Rule 603.f .				Date: 08/04/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Waldron, Emily

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient		Inadequate	
Comment:	Berm is not consolidated. Plastic liner pieces incorporated into loose soil.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Comply with Rule 603.f .			Date:	08/04/2017

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 223587 Type: WELL API Number: 081-06954 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: No current MIT on record or delinquent as required by Rule 326. Well has been shut-in since September 2015. MIT will be needed this September 2017.

Corrective Action: _____ Date: _____

Facility ID: 285519 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed.
No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 285519 Lat: 40.389080 Long: -108.136300

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: g**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	285519	200092804	

COGCC Comments

Comment	User	Date
The land farm area mentioned in previous inspections appears to have recently been removed. Please follow environmental Corrective Actions found in inspection report document number 677900246 in addition to the ones found in this report.	waldrone	08/10/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401372246	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222881

689800129	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222875
-----------	-------------------	---

