

Inspection Photos
Location ROBBINS 24-11A
API:05-001-07577



FENCE DOWN



SOILED DIRT INSIDE PUMP JACK HOUSE