

Inspection Photos

8/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323052

Inspection Doc. Number: 675103879

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323052



Photo 1: Photo taken from the south end of the well location, facing north. Photo shows no reclamation per corrective actions have been conducted; access road remains, location remains predominantly undesirable weedy plant species such as kochia.



Photo 2: Photo taken from the adjacent reference area. Photo shows alfalfa crop growing in reference area.



Photo 3: Photo taken from the battery location. Photo shows sediment deposition from sediment laden stormwater runoff degrading the location. 6 foot measuring stick for reference



Photo 4: Photo shows gully erosion continuing to form and degrade the location and access road. Inspection doc. #682502370 required operator to repair erosion and install/repair required BMPs. CA has not been addressed. 6 foot measuring stock for reference.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323052



Photo 5: Photo shows gully erosion continuing to form and degrade the location and access road. Inspection doc. #682502370 required operator to repair erosion and install/repair required BMPs. CA has not been addressed. 6 foot measuring stock for reference.



Photo 6: Photo shows gully erosion continuing to form and degrade the location and access road. Inspection doc. #682502370 required operator to repair erosion and install/repair required BMPs. CA has not been addressed. 6 foot measuring stock for reference.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323052



Photo 5: Photo shows gully erosion continuing to form and degrade the location and access road. Inspection doc. #682502370 required operator to repair erosion and install/repair required BMPs. CA has not been addressed. 6 foot measuring stock for reference.



Photo 6: Photo shows gully erosion continuing to form and degrade the location and access road. Inspection doc. #682502370 required operator to repair erosion and install/repair required BMPs. CA has not been addressed. 6 foot measuring stock for reference.