

**Inspection Photos**  
**Location Name: Centennial 32-33**  
**API: 05-123-21239**



**Photo 1: Location, looking NE**



**Photo 2: Wellhead looking SW**

Inspection Photos  
Location Name: Centennial 32-33  
API: 05-123-21239



Photo 3: Separator not anchored



Photo 4: Concrete vault not anchored



**Inspection Photos**  
**Location Name: Centennial 32-33**  
**API: 05-123-21239**



**Photo 5: Riser at wellhead.**