


Inspection Photos
Location Name: Bucklin 9-36
API: 05-123-13590



Wellhead looking west, no wellhead sign present



Wellhead looking east, no wellhead sign present

Inspection Photos
Location Name: Bucklin 9-36
API: 05-123-13590



Tank battery sign looking east



Battery looking east from west side of separator

Inspection Photos
Location Name: Bucklin 9-36
API: 05-123-13590



Battery looking west from northeast edge of tank berm