

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2017

Submitted Date:

08/14/2017

Document Number:

678300867

**FIELD INSPECTION FORM**

Loc ID 336275 Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: K P KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451672	TANK BATTERY	AC	08/09/2017		-	UPRR 42 Pan Am K battery	EI

**General Comment:**

multiple operators equipment and wells on same location. Kauffman well(s) associated with battery not colocated with battery and not inspected at this time.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	weeds in and around fired vessel a shown in attached photo		
Corrective Action:	Comply with Rule 603.f .	Date:	08/24/2017

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Tank	<= 1 bbl	
Comment:	hydrocarbon stained soils near eastern KPK crude tank with apparent leak at bottom seam of tank as shown in attached photo		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Repair, remove or replace leaking crude tank		Date: 09/14/2017

In Containment: Yes

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	DCP meter run identified as coming from UPRR 42 Pan Am K production		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	unused untagged not locked out risers at sales point of UPRR 42 Pan AM K production as shown in attached photo		
Corrective Action:	Comply with Rule 603.f . within 24 hours to lock out tag out unused risers and 30 days to remove unused risers		Date: 09/14/2017
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 6	
Comment:	unused untagged not locked out risers south of sales point of UPRR 42 Pan AM K production as shown in attached photo	
Corrective Action:	Comply with Rule 603.f . within 24 hours to lock out tag out unused risers and 30 days to remove unused risers	Date: 09/14/2017

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 451672 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401375245	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226123">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226123</a>
678300868	stained soils	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226118</a>
678300869	weeds	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226119</a>
678300870	unused risers gas sales point	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226120">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226120</a>
678300871	Unused risers S of gas sales point	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226121</a>