

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2017

Submitted Date:

08/14/2017

Document Number:

689800166

**FIELD INSPECTION FORM**

Loc ID 312987 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 33825  
Name of Operator: GEOTECH PRODUCTION INC  
Address: 7844 S ESPANA WAY  
City: AURORA State: CO Zip: 80016-

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
henderson, ralph	(303) 690-0921	hap7844@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223186	WELL	PR	06/01/2016	GW	081-06548	SPETTER 5-8	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. No label on tank.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/07/2015
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No battery sign on location.		
Corrective Action:		Date:	05/07/2015

**Emergency Contact Number:**

Comment:	303-888-7373		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Type: Gas Meter Run	# 1		
Comment:	40.66917, -107.52279		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	40.66917, -107.52279		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	2 - 1" and 2 - 2" steel risers observed at 40.66899, -107.52255 not marked for abandonment or locked out tagged out.		
Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."	Date:	06/08/2016

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1				40.669150,-107.522650

Comment:		
Corrective Action:		Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm around tank.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 05/07/2015

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 223186 Type: WELL API Number: 081-06548 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion occurring along western side of location. Containers stored without secondary containment. No stormwater BMPs observed.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 05/07/2015

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Follow up to inspection from 7/11/2016 document number 673403396. Location has been mowed, wildlife protection has been installed, and production records are current. All other corrective actions from that report remain outstanding.	waldrone	08/14/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401375743	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226646">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226646</a>
689800167	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226640">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226640</a>