

Final Reclamation Inspection

August 16, 2017

Operator: TOP OPERATING COMPANY FDBA MURRAY J HERRING LTD - 39560

API: 05-123-08139

Weld County, CO

NENE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 1. Photo taken from the eastern battery location, facing North, towards the meter shed. Comply with the Pipeline/Flowline NTO and/or the Reclamation Rule 1004.a to remove (regardless of ownership) all equipment.




Photo 2. Photo taken just west of the meter shed, facing North. Comply with the Pipeline/Flowline NTO and/or the Reclamation Rule 1004.a to remove (regardless of ownership) all equipment. See Photo 3 regarding pipe risers.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 3. Photo taken of three (3) pipe risers that were previously mentioned in Photo 2.



Photo 4. Photo taken from the eastern battery location, facing South. Weedy, annual vegetation (Kochia and Russian thistle) observed throughout the battery location. Photo further illustrates that reclamation activities have not been performed because gravel still remains.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 5. Photo taken from the eastern battery location, facing West. Weedy, annual vegetation (Kochia and Russian thistle) observed throughout the battery location. Photo further illustrates that reclamation activities have not been performed because gravel still remains.



Photo 6. Photo taken from the central battery location, facing West. Weedy, annual vegetation (Kochia and Russian thistle) observed throughout the battery location. Photo further illustrates that reclamation activities have not been performed because gravel still remains from the access road.