

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2017

Submitted Date:

08/17/2017

Document Number:

680302253

FIELD INSPECTION FORM

Loc ID 313873 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 79905
Name of Operator: SMITH OIL PROPERTIES INC
Address: PO BOX 219
City: BYERS State: CO Zip: 80103

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Shelley, Vicki	303-825-7405	smithoilprop@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
226642	WELL	PR	06/01/2015	GW	087-07380	J. A. FARMS 1	PA

General Comment:

P&A Day (3) final. Well has been cut-off @ (6') below grade, capped and buried. **SATISFACTORY**
NOTE TO OPERATOR: Submit Subsequent Form 6 via COGCC e-form. Remove all equipment from location. Contact COGCC Environmental for closure directives. Contact COGCC Reclamation Group for directives. Begin reclamation process.

Location			
Lease Road:			
Type	Other		
comment:	Begin reclamation process. Contact COGCC Reclamation Group for directives.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	Remove all equipment from location. Contact COGCC Environmental and COGCC Reclamation for directives.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 226642 Type: WELL API Number: 087-07380 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: 970-522-3078

Surface Casing

Cement Volume (sx): 50+15

Circulate to Surface: YES

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): 2+40+40

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 5000,1400,217,30

Cement Volume (sx): 2+40+40+50+15

Good Return During Job: YES

Cement Type: G

Comment: Tagged @ 102', mixed (15) sks cement plug, topped off casing to surface. Pumped flow-line clean, excavated/cut off @ (6') capped and backfilled. P&A Completed SATISFACTORY For full P&A details see previous days FIR's.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management. Begin reclamation process. Contact COGCC Reclamation for directives.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
P&A Completed SATISFACTORY. NOTE TO OPERATOR: Submit Subsequent Form 6, Remove all equipment from location, Contact COGCC Environmental and COGCC Reclamation for directives. Begin reclamation process.	schureky	08/17/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401379303	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4230188