

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2017

Submitted Date:

08/15/2017

Document Number:

681700794

FIELD INSPECTION FORM

Loc ID 320206 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 87195
Name of Operator: TEXAS TEA OF COLORADO LLC DBA TEXAS TEA LLC
Address: 14405 W. COLFAX #298
City: LAKEWOOD State: CO Zip: 80401

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203037	WELL	SI	06/04/2012	OW	001-08443	R C NAUMAN 4	EI

General Comment:

COGCC environmental unit inspection to document existing conditions at orphaned well. No changes observed at well head or tank battery since previous Field Inspection Report (document #681700524). Operator's registration and right to conduct oil and gas operations in the state of Colorado were revoked under COGCC OFV 1V-573.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Wellhead sign has been marked with COGCC emergency contact info.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	COGCC contact information provided at well sign and electrical boxes WNW of wellhead.		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	Uncontrolled weeds at wellhead.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wellhead sitting in small excavation. Wellhead equipment open to atmosphere (three 2", unplugged openings and two 1" uncapped valves). See photos.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: Localized, oil-stained soil at wellhead (see photos).

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	# 4		corrective date
Comment:	Electrical boxes and transformers WNW of wellhead.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 203037 Type: WELL API Number: 001-08443 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401376889	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227530
681700795	wellhead and sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227520
681700796	view of wellhead from SE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227521
681700797	stained soil at wellhead (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227522
681700798	stained soil at wellhead (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227523
681700799	2" valve on north side of wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227524
681700800	COGCC Contact info at electrical boxes	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227525
681700801	transformers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227526
681700802	exposed valves on south side of wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227527