



photo 1: Facing north at the beginning of the access road.



photo 2: Facing north along the access road. The location is toward the upper left side of the photo.



photo 3: There are stormwater BMP's in place at the east side of the location.



photo 4: Facing southwest toward the location.



photo 5: There is gravel that remains at the location.



photo 6: Facing southwest toward the cut slope.



photo 7: Facing west toward the cut slope. The vegetation is beginning to establish in this area.



photo 8: West side of the location facing east overlooking the location.