

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2017

Submitted Date:

08/15/2017

Document Number:

689100036

FIELD INSPECTION FORM

Loc ID 443091 Inspector Name: LUJAN, CARLOS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Barberis, Marcelo	713-372-0289	bmal@chevron.com	CEMC
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Neidel, Kris		kris.neidel@state.co.us	EPS, NW Region

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443091	LOCATION	AC	08/31/2015		-	Terraced Area Wilson Creek 443091	EI

General Comment:

Environmental inspection conducted as a follow-up to the ongoing remediation project. On site with Maracel Barberis (Chevron EMC) and Brent Lucyk (Stantec). Sunny and warm, around 80 oF. The seven terraces have been excavated, sampled, and backfilled. Leveling is in progress and terraces will be covered with top soil and seeded. COGCC staff requested a brief progress report by the end of August (mid september at the latest), prior to the final report to be submitted when all activities have been completed. Landowner has requested that the road be left in place for his beneficial use. Chevron was instructed to submit an e-form 04 Sundry Notice with a variance request.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 443091 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: COGCC staff requested a brief progress report by the end of August (mid-September at the latest), prior to the final report to be submitted when all activities have been completed.

Corrective Action: Submit via supplemental e-form 27 a brief progress report describing completed activities and pending activities to complete reclamation work. Note: REM #9622.

Date: 09/15/2017

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
	lujanc	08/15/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401377289	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227787
689100037	Photo Report Chevron Terraces	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227781