

- Sanchez 3 05-067-05341



Photo 1: Steel line – disconnected and open on both ends.

- Sanchez 3 05-067-05341



Photo 2: Disconnected 1" steel line.

- Sanchez 3 05-067-05341



Photo 3: Debris

- Sanchez 3 05-067-05341



Photo 4: Electrical service panel and power pole.

- Sanchez 3 05-067-05341



Photo 5: Power poles

- Sanchez 3 05-067-05341



Photo 6: Line broken off power pole at top of location.

- Sanchez 3 05-067-05341



Photo 7: Steel riser in back tank containment berm.

- Sanchez 3 05-067-05341



Photo 8: Connected flowline at tank.

- Sanchez 3 05-067-05341



Photo 9: Impacted soil at tank drain.

- Sanchez 3 05-067-05341



Photo 10: Tank marked empty.