

- JCK 4 05-067-06511



Photo 1: Wellhead signs, sediment flow, and flowlines.

- JCK 4 05-067-06511



Photo 2: Stormwater flow off NE corner of location.

- JCK 4 05-067-06511



Photo 3: Steel cable in perimeter ditch along E side of location.

- JCK 4 05-067-06511



Photo 4: Steel cable over E edge of fill slope.

- JCK 4 05-067-06511



Photo 5: Steel pipe and cable over E edge of fill slope.

- JCK 4 05-067-06511



Photo 6: Erosion gully 1 of 3 from breach in berm along E side of location.

- JCK 4 05-067-06511



Photo 7: Erosion gulley 2 of 3 from breach in berm on E side of location.

- JCK 4 05-067-06511



Photo 8: Erosion gulley 3 of 3 from breach in berm in SE corner of location.

- JCK 4 05-067-06511



Photo 9: South access road.

- JCK 4 05-067-06511



Photo 10: Erosion channel in S access road carrying stormwater and sediment down slope. Flow hits breach in berm and flows off SE corner of location.

- JCK 4 05-067-06511



Photo 11: North access road.

- JCK 4 05-067-06511



Photo 12: Erosion channels in N access road carrying stormwater and sediment flow onto location.

- JCK 4 05-067-06511



Photo 13: Stormwater and sediment flow onto location from N access road.

- JCK 4 05-067-06511



Photo 14: Sediment deposit around well head as it flows into ditch along E side of location and off NE corner of location.